

**รายละเอียดแนบท้ายใบรับรองห้องปฏิบัติการทดสอบ**  
**ที่ 20T099/1077**

ชื่อห้องปฏิบัติการ : บริษัท เอสจีเอส (ประเทศไทย) จำกัด ห้องปฏิบัติการทดสอบชิ้นส่วนยานยนต์  
ที่อยู่ : 300/109 หมู่ที่ 1 นิคมอุตสาหกรรมอีสเทิร์นซีบอร์ด ตำบลตาสีห์  
อำเภอปลวกแดง จังหวัดระยอง

หมายเลขการรับรองที่: ทดสอบ 0486

สถานภาพห้องปฏิบัติการ  ถาวร  นอกสถานที่ ชั่วคราว เคลื่อนที่

สาขาการทดสอบ	รายการทดสอบ	วิธีทดสอบ
สาขาชิ้นส่วนยานยนต์		
1. Trim materials in interior of automobiles	- Fogging characteristics <ul style="list-style-type: none"> <li>● Photometric</li> <li>● Gravimetric</li> </ul>	- Inhouse Method SAE J1756 : 2006 - Inhouse Method ISO 6452 : 2007
2. Interior Materials of Automotive	- Flammability	- FMVSS 302 : 2017 - ISO 3795 : 1989 - SAE J369 : 2019 - NES M0094 : 2018-1 - TSM0500G : 2015 (REV.15) - BSDM0500 : 2015 (REV.3)
3. Interior trim components of Automotive	- Accelerated exposure using a controlled irradiance xenon-arc Apparatus	- SAE J2412 <sup>TM</sup> : 2015
4. Paints and varnishes	- Determining of the gloss of coatings	- ISO 2813 : 2014
5. Paints and varnishes	- Film hardness by pencil test	- ISO 15184 : 2012 - ASTM D 3363 – 05 (Reapproved 2011)e <sup>2</sup>
6. Metals, metallic coatings and alloys	- Neutral salt spray test	- ISO 9227 : 2017

รายละเอียดแนบท้ายใบรับรองห้องปฏิบัติการทดสอบ  
ที่ 20T099/1077

หมายเลขการรับรองที่ : ทดสอบ 0486

สถานภาพห้องปฏิบัติการ  ถาวร  นอกสถานที่  ชั่วคราว  เคลื่อนที่

สาขาการทดสอบ	รายการทดสอบ	วิธีทดสอบ
สาขาชิ้นส่วนยานยนต์		
7. Paints and varnishes	-Paints and varnishes – Cross-cut test (Hand-held Multi-blade cutting tool)	- ISO 2409 : 2013
8. Non-cellular plastics	-Determining of the density of non-cellular plastic (Method A Immersion method)	- ISO 1183-1 : 2019
9. Metals, metallic coatings and alloys	-Accelerated corrosion test- Atmospheric corrosion	- STD 4319 : 2017
10. Materials, coatings, and interactions materials	-Cyclic Corrosion Test	- CETP 00.00-L467 : 2009

ออกให้ ณ วันที่